MPP/URF 19-757

Under Review Notification

Product #: Dart Tooling BELL

Raised By: VANESSA MOREL

Product Name: 407 FIELD MAINTENANCE KIT

Date: 19.05.31

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & Current Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBT18561	RBT18561 REV 3	Y	Y	N	Y	N	N	N	19-757	SEE BELOW

Description of Issue:

ITEM RBT18561-45 MUST BE EITHER REMOVE OR REPLACE BY WITH A HIGHER QUALITY TOOL

ITEM RBT18561-77 FOAM CUTOUT TO BE EITHER REMOVE OR CHANGED

ITEM RBT18561-81 NEED TO BE MODIFY ACCORDINGLY

KIT RBT18561 MUST BE PLACE IN QUARANTINE TILL ENGINEERING RELEASE NEW DRAWING

Distribution:

VP Operations	Director of Engineering	Customer Support Manager	Technical Support
Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene

Linda Lacelle

From: Daniel Paquette
Sent: Wednesday, July 31, 2019 11:15 AM
To: Linda Lacelle
Cc: Jennifer Renwick; Marie Lajeunesse; David Duval
Subject: RE: URF 19-757 (RBT18561)

As per ECN previous parts satisfactory. The -45 is a 6-TT30 that we purchase from MAIN INDUSTRIAL. Correction, they do not need to be reworked, they just need to be re stocked as 6-TT30 . The engraving can be done later when a -45 is required.

From: Linda Lacelle <llacelle@dartaero.com>
Sent: Wednesday, July 31, 2019 11:03 AM
To: Daniel Paquette <dpaquette@dartaero.com>
Cc: Jennifer Renwick <jrenwick@dartaero.com>; Marie Lajeunesse <mlajeunesse@dartaero.com>; David Duval <dduval@dartaero.com>
Subject: RE: URF 19-757 (RBT18561)

But there are 3 parts affected...why do these need to be "parts must comply" ?? we have sold 12 of these since Plex..???

From: Daniel Paquette <dpaquette@dartaero.com>
Sent: Wednesday, July 31, 2019 11:00 AM
To: Linda Lacelle <llacelle@dartaero.com>
Cc: Jennifer Renwick <jrenwick@dartaero.com>; Marie Lajeunesse <mlajeunesse@dartaero.com>; David Duval <dduval@dartaero.com>
Subject: RE: URF 19-757 (RBT18561)

Sorry I meant ECN19-757. This is the one I showed you earlier, we need to re work RBT18561-45 (engraving) the re work opp. Is in the routing. Thanks.

From: Daniel Paquette
Sent: Wednesday, July 31, 2019 10:53 AM
To: Linda Lacelle <llacelle@dartaero.com>
Cc: Jennifer Renwick <jrenwick@dartaero.com>; Marie Lajeunesse <mlajeunesse@dartaero.com>; David Duval <dduval@dartaero.com>
Subject: FW: URF 19-757 (RBT18561)

R & B updated to Rev G.

From: Vanessa Morel <vmorel@dartaero.com>
Sent: Friday, May 31, 2019 2:27 PM
To: Linda Lacelle <llacelle@dartaero.com>; Ketan Tailor <ktailor@dartaero.com>; Chantal Lavoie <clavoie@dartaero.com>; Daniel Paquette <dpaquette@dartaero.com>; Dart Sales <dartsales@dartaero.com>; David Duval <dduval@dartaero.com>; Frederick Leblanc <fleblanc@dartaero.com>; Jean Francois Cadieux <jcadieux@dartaero.com>; Jean Francois Sauve <jfsauve@dartaero.com>; Jean-Luc Menard <jmenard@dartaero.com>; John Chuprun <jchuprun@dartaero.com>; Konrad Sauve <ksauve@dartaero.com>; Marcel Daviau <mdaviau@dartaero.com>; Marie Lajeunesse <mlajeunesse@dartaero.com>; Michael Lee <mlee1@dartaero.com>; Michelle GagnonDonovan <mgagnondonovan@dartaero.com>; Mychel Beauregard <mbeauregard@dartaero.com>; Patrick Duval <pduval@dartaero.com>; Regis Quenneville <rquenneville@dartaero.com>; Robert Aboud <raboud@dartaero.com>; Ross Black <rblack@dartaero.com>; Steven Drouin <sdrouin@dartaero.com>; Steven Hemmerich <shemmerich@dartaero.com>; Support Eugene <support.or@dartaero.com>; Support Hawkesbury <support.on@dartaero.com>
Subject: URF 19-757 (RBT18561)

Hi Everyone,

Please be advised that the following kit is now under review
Let me know if you have any questions.

Thanks,

Vanessa Morel
Mechanical Designer

DART AEROSPACE
T 1 613 632-5200 Ext.302
E vmorel@dartaero.com
W www.dartaerospace.com